



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

December 15, 2015

Kerry Goodballet, Director of Permitting
CONSOL Energy Inc.
CNX Center
1000 CONSOL Energy Drive
Canonsburg, PA 15317

Subject: Adjacent Area Legal Description Errors, CONSOL Mining Company, LLC,
Emery Deep Mine, C/015/0015

Dear Ms. Goodballet:

The Division has identified two typos in the legal description for the adjacent area for the Emery Mine which must be corrected on page 1, Chapter IV of the Mine and Reclamation Plan. The boundary of the adjacent area is shown on Plate III-9 and was used to verify the information. It appears a portion of the NE $\frac{1}{4}$ SW $\frac{1}{4}$ should be included in Township 22 South, Range 6 East, Section 23 and a comma is erroneously located between the S $\frac{1}{2}$ and the SW $\frac{1}{4}$. We are providing a redlined copy of this page to further depict the error and facilitate the correction.

Please submit a permit revision, with C1 and C2 forms that update Page 1 of Chapter IV with the correct legal description. In return, the Division will update the permit to reflect said changes.

If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron Haddock
Coal Program Manager

DRH/LR/ss

Enclosure

O:\015015.EME\EmeryDeepLegalDescriptionLtr. (1).doc

CHAPTER IV ENGINEERING DESIGNS

IV.A UNDERGROUND MINE PLAN

This part covers the description of the underground mining operations to be conducted at the Emery Mine.

IV.A.1 UNDERGROUND MINE PLAN

UMC 783.12(a), 783.24(c), 783.25(e), 783.25(h), 784.11(a), 784.23(a)

The Adjacent Area for the Emery Mine encompasses approximately 5,776 acres. The permit area for the Emery Mine encompasses approximately 442.5 acres. The boundary of the Adjacent Area and permit area is shown on the Permit Boundaries and Bonding Map (Plate III-9). The description of the Adjacent area is as follows:

Township 22 South, Range 6 East

Section 19: S/2NE/4, SE/4, E/2SW/4

Section 20: S/2NE/4, SE/4NW/4, S/2

Section 21: S/2N/2, S/2

Section 22: S/2, SW/4NW/4, portions of the following E/2SE/4NW/4, SW/4SE/4NW/4, S/2NW/4NE/4, SW/4NE/4, SW/4SW/4NE/4NE/4, W/2SE/4NE/4, S/2NE/4SE/4NE/4, SE/4SE/4NE/4

Section 23: portions of the following SW/4NW/4, NW/4SW/4

Section 24: S/2, SW/4

Section 26: NW/4NW/4

Section 28: All

Section 29: All

Section 30: E/2, E/2NW/4, SW/4NW/4, N/2NW/4SW/4, E/2SW/4

Section 31: N/2, W/2SW/4, E/2SE/4, SW/4SE/4

Section 32: All

Section 33: W/2, NE/4

Remove Comma.
Should be S1/2
SW1/4.

Looks like part of NESW too.

The description of the permit area is as follows:

Township 22 South, Range 6 East

Section 27: portions of NW/4, SW/4, NE/4

Section 30: portions of NE/4

Section 32: portions of NW/4, NE/4, SE/4

Section 33: portions of NW/4, NE/4, SW/4

Mining operations at the Emery Mine are conducted in the IJ Zone utilizing the room and pillar mining method. Plate IV-1 shows the layout, the present mine workings and the projected areas to be mined during the permit term. The existing workings have been marked to show the extent of underground mining operations (1) before August 3, 1977, (2) between August 3, 1977 and May 3, 1978, and (3) after May 3, 1978 up to the permit approval date of January 5, 1986. There are no surface mining operations at the Emery Mine. The projected mine workings are delineated by year for the next five year permit term. Plate IV-2 shows the same plan on a 1"=1000' map to show the extent of the projected life of mine plan in the IJ Zone. The Emery Mine operates under the General Safety Orders, Utah Coal Mines issued by the Industrial Commission of Utah and the applicable regulations issued by the Mine Health and Safety Administration (MSHA).

Access to the underground workings is through the portals shown on Plate II-1. All of the present portals are drift openings at the outcrop of the seam. These openings consist of intake, return, and belt entries. It may be necessary in the future to install ventilation raises in other areas of the property; however, these locations are not known at the present time. Future portals may consist of ramp excavations and shafts to access the coal seam. The new 4 East portal will use a ramp excavation down to the top of the IJ seam. A new set of portals will be installed for the southern main entries of the mine when production from the southern part of the mine warrants it.

Revised 8-31-95
Revised 4/05
Revised 3/07
Revised 5/09
Revised 9/09
Revised 04/10

INCORPORATED

MAY 06 2010